## FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT X=SHOP, V=VENDOR, O=OTHER

MONTH

| MARCH      |   |     |           |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    |             |   |
|------------|---|-----|-----------|---|---|---|---|---|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|-----|----|----|-------------|---|
| Equip<br># | 1 | 2   | 3         | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29  | 30 | 31 | Equip<br>#  | COMMENTS:   |
| A16        |   |     |           |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | A16         |   |
| Bobcat963  |   |     | Π         |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | Bobcat963   | Replaced shaft/drum, sprocket, key stock, bolt and both bearings assembl  |
| BR75       |   |     | Π         |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | BR75        |   |
| BR77       |   |     | Π         |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | <b>BR77</b> |   |
| BR94       |   |     | Π         |   |   |   |   |   |   |    | X  |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | BR94        | R&R master switch: Cleaned and checked all battery connections.   |
| BS82       |   |     | Π         |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    | X  |    |    |     |    |    | BS82        | R&R flex plate: Recharged A/C.  |
| B4315      |   |     | Π         |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | B4315       |   |
| B4316      |   |     | Π         |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    | X  |    |    |    |    |    |    |    |    |    |     |    |    | B4316       | R&R cruise control, installed new clock spring and control switch: R&R passenger door handle.   |
| C4300      |   |     | H         |   |   |   |   |   |   | T  |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    | X   |    |    | C4300       | Performed B-service: Rotated tires and set all 5 tire pressures.  |
| D4301      |   |     | H         |   |   |   |   |   |   | T  |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | D4301       |   |
| D4305      |   |     | H         |   |   |   |   |   |   | T  |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | D4305       |   |
| Engine 6   |   |     | H         |   |   |   |   |   |   | T  |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | Engine 6    |   |
| E282       |   |     |           |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | E282        |   |
| E288       |   |     |           |   |   |   |   |   |   |    |    |    |    |    |    |    |    | X  |    |    |    |    |    |    |    |    |    |    |     |    |    | E288        | R&R steering U-joints on steering box: R&R passenger side front brake<br>pad: R&R engine cooler clamp and alt mounting bolt.                  |
| E294       |   |     |           |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | E294        | pad. Acer ongine cooler champ and ar mounting ook.  |
| E295       |   |     |           |   |   |   |   |   |   | X  |    |    |    |    |    |    |    |    | X  |    |    |    |    |    |    |    |    |    |     |    |    | E295        | R&R power wire to foam controller: R&R fuse in TA and reel line knob:   |
| E71        |   |     |           |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | E71         |   |
| E72        |   |     |           |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     | X  |    | E72         | R&R A/C system: Performed and passed leak test.   |
| E73        |   | X   |           |   |   |   |   |   | X |    |    |    |    |    |    |    |    |    |    | X  |    |    |    |    |    |    |    |    |     |    |    | E73         | Cut and fabricated circular saw mounting base: Cleaned and lubricated rear tool slide out track: R&R batteries: R&R 2 way radio headsets.     |
| E74        |   |     |           |   |   |   |   |   |   |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | E74         | real tool shall out mark. Real ballones, Real 2 way had o houdbers.   |
| E75        |   | İ – | $\square$ | 1 |   |   |   |   |   | T  | T  |    |    |    |    |    | 1  |    |    |    |    |    |    |    |    |    |    |    | İ – | ſ  |    | E75         |   |
| E77        |   | İ – | $\square$ | ╡ |   |   |   |   |   | T  | T  |    |    |    |    | Ť  | 1  |    |    |    |    |    |    |    |    |    | x  |    | İ – | ſ  |    | E77         | Replaced both front hub oil red caps and topped off oil level.  |
| E82        |   | İ – | $\square$ | ╡ | X |   |   |   |   | T  | T  |    |    |    |    | x  | 1  |    |    |    |    |    |    |    |    |    |    |    | X   | ſ  |    | E82         | Removed front brakes and installed new front brake spring kits, cleaned s<br>cams and installed front brake pads & drums: R&R all batteries.  |
| E83        |   |     |           |   | X |   |   |   |   | X  |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | E83         | Replaced rear brake and all 4 rear tires: Replaced left rear abs sensor:<br>R&R brass door latch, O-ring on compressor and ABS sensor on rear |
| E84        |   |     |           |   |   |   |   |   |   | Γ  |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |     |    |    | E84         | reaction and a solution of the on compression and the sensor on real  |
| E85        |   |     | $\square$ |   |   |   |   |   | ┢ | t  |    |    |    |    |    |    | ┫  |    |    |    |    |    |    |    |    |    |    |    |     |    |    | E85         |   |

## FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT X=SHOP, V=VENDOR, O=OTHER

| E86     |   |          |   |           |  |   |   | Х |   |   | 1 | I |            | T        |           | 1 | T | I | Т |   | Т |   | T |            | I | I            |   | E86     | R&R passenger side front inside cab light: R&R passenger side rear  |
|---------|---|----------|---|-----------|--|---|---|---|---|---|---|---|------------|----------|-----------|---|---|---|---|---|---|---|---|------------|---|--------------|---|---------|---|
|         |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   |         | fender flare.   |
| E87     |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            | х |              |   | E87     | Replaced driver side scene light bulb.  |
| E89     | X |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              | х | E89     | R&R bent exhaust pipes and exhaust hangers: Replaced the damaged<br>Magna grip exhaust tip for main engine: R&R Kusmaul.  |
| E90     |   |          |   |           |  |   |   |   |   |   | 2 | X |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | E90     | Pulled engine our of sand with D43, inspected vehicle all ok.   |
| E94     |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | E94     |   |
| E95     |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | E95     |   |
| E96     |   |          |   |           |  |   |   |   |   |   |   | T |            |          |           |   |   |   |   |   |   |   |   |            |   | X            |   | E96     | Performed B-service: Replaced all four drive tires: Replaced both A/C sharter valves and recharged A/C system.            |
| E4361   |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | E4361   |   |
| E4354   |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | E4354   |   |
| IT      |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | IT      |   |
| L87     |   |          | 1 |           |  |   |   |   |   |   |   |   | X          |          |           |   |   |   |   |   |   |   |   |            |   |              |   | L87     | R&R EPU.  |
| P22A    |   |          | 1 |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P22A    |   |
| P22B    |   |          | 1 |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P22B    |   |
| P22C    |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P22C    |   |
| P4323   |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P4323   |   |
| P71     |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P71     |   |
| P74 523 |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P74 523 |   |
| P75 522 |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P75 522 |   |
| P77     |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P77     |   |
| P86     |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | P86     |   |
| PIO-1   |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | PIO-1   |   |
| POOL    |   |          |   |           |  |   |   |   |   |   |   |   |            |          |           |   |   |   |   |   |   |   |   |            |   |              |   | POOL    |   |
| R4330   |   |          | 1 |           |  |   |   |   |   | T | T | ↑ |            | İ        |           |   | T | ╡ |   |   |   |   |   | T          | T | 1            |   | R4330   |   |
| R4332   | х |          | ┢ |           |  |   | T | ╈ |   | ╡ | ╡ |   |            | T        | Π         |   |   | 1 |   |   |   |   |   | Τ          | T |              |   | R4332   | Performed C-service: Replaced engine oil and oil filter, two fuel filter,<br>drain and fill front and rear differentials. |
| R4333   |   |          | 1 |           |  |   |   | T | 1 | T |   |   |            | l        |           |   |   |   |   | 1 | T |   |   | T          | Ì | İ.           |   | R4333   |   |
| R87     |   | $\vdash$ | ┢ | F         |  | + |   | ╈ | ╈ | ╈ | ╈ | ╈ |            | $\vdash$ | $\square$ |   | ╡ | ╡ |   | ╈ | ╈ | ┢ | + | $\top$     | ┢ |              |   | R87     |   |
| Relief  |   | $\vdash$ | ╈ | $\square$ |  | ╡ |   | ╈ | ╈ | ╈ | ╋ | ╈ | $\uparrow$ | $\vdash$ |           |   | ╡ | ┥ |   | ╈ | ╉ | ╈ | 1 | $\uparrow$ | ┢ | $\mathbf{T}$ |   | Relief  |   |
| S4310   |   |          | ┢ |           |  | ╡ | ╉ | ╉ | + | ╈ | ╈ |   | +          |          |           |   | 1 |   |   | + |   |   | ╈ | +          | ┢ | $\mathbf{T}$ |   | S4310   |   |

## FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT X=SHOP, V=VENDOR, O=OTHER

| SQ287 |   |   |   |   |  |   |   |    | X |   | X |  |   |  |  |   |   | SQ287 | Repaired broken wire for reverse lights: Plugged driver side inside dual tire: R&R front rotors.   |
|-------|---|---|---|---|--|---|---|----|---|---|---|--|---|--|--|---|---|-------|--|
| T4327 |   |   |   |   |  |   |   |    |   |   |   |  |   |  |  |   |   | T4327 |  |
| T4328 |   |   |   |   |  |   |   |    |   |   |   |  |   |  |  |   |   | T4328 |  |
| TR43  |   | Γ | x |   |  |   |   |    |   |   |   |  |   |  |  |   |   | TR43  | Hooked truck up to trailer for DOT inspections: R&R air purge valve on<br>air dryer.   |
| U-11  |   | Γ |   |   |  |   | Γ |    |   |   |   |  |   |  |  |   |   | U-11  |  |
| U-17  |   |   |   |   |  |   |   |    |   |   |   |  |   |  |  |   |   | U-17  |  |
| U-18  |   |   |   |   |  |   |   |    |   |   |   |  |   |  |  |   |   | U-18  |  |
| U-19  |   | T |   |   |  |   |   | ľ  |   |   |   |  |   |  |  | Ì |   | U-19  |  |
| U4348 |   |   |   |   |  |   |   |    |   |   |   |  |   |  |  |   |   | U4348 |  |
| U-30  |   |   |   |   |  |   |   |    |   |   |   |  |   |  |  |   |   | U-30  |  |
| WT72  |   |   |   |   |  |   |   |    | x |   |   |  |   |  |  | X |   | WT72  | Removed all 4 rear tires on last axle: Dismounted and mount 4 new tires:<br>Adjusted pump packing: Aligned steering wheel & set front tires. |
| WT82  |   |   |   |   |  |   |   |    |   |   |   |  |   |  |  |   |   | WT82  |  |
| WT83  |   |   |   | X |  |   |   |    |   |   |   |  |   |  |  |   |   | WT83  | Performed C-service: Resealed rocker box, injectors all STC injector oil feed "O" rings and replaced front & rear motor mounts.              |
| WT86  | Π |   |   |   |  | T |   |    |   |   |   |  |   |  |  |   |   | WT86  |  |
| WT90  |   | T |   |   |  |   | 1 | İ. |   | X |   |  |   |  |  |   | Π | WT90  | R&R passenger side front compartment door.   |
| WT93  |   | T |   |   |  |   | 1 | İ. |   |   |   |  |   |  |  |   | Π | WT93  |  |
| WT96  |   | T |   | 1 |  |   | 1 | İ  |   |   |   |  | 1 |  |  |   | Π | WT96  |  |