

**FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT**  
**X=SHOP, V=VENDOR, O=OTHER**

**MONTH**  
**MAY 2018**

Equip #	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Equip #	COMMENTS:
A16																																A16	
BR74																														X		BR74	Preformed compliance inspection.
BR75																																BR75	
BR77																																BR77	
BR94																																BR94	
BS82																																BS82	
B4315																																B4315	
B4318																																B4318	
C4300											X																					C4300	Replaced fan belt & tensioner and idle pulley: AC belt flushed .
D4301																																D4301	
D4305																																D4305	
Engine 6																																Engine 6	
E282																																E282	
E288																			X													E288	Recharged AC system.
E294																																E294	
E295																																E295	
E71																																E71	
E72												X																				E72	Tightened loose hose clamps on foam lines: R&R p-side bumper ground light.
E73																																E73	
E74																																E74	
E75																																E75	
E77		X																														E77	R&R turn signal switch on column.
E82															X																	E82	Replaced four drive tires and valve stems.
E83																														X		E83	Adjusted main pump packing
E84																																E84	
E85																																E85	
E86																													X			E86	Recharged AC system.

**FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT**

**X=SHOP, V=VENDOR, O=OTHER**

E87																			X															X	E87	R&R Akron valve for leaking: R&R right rear wheelmen read ER light assembly: Replaced intake heater solenoid 1 & 2.	
E90																																		X	E90	R&R reel line swivel for leaking water: B-service, replaced engine oil & filter, air & fuel filter: R&R switch on back pump gear box.	
E93																																			E93		
E94			X																																E94	Removed front bumper line: Replaced front head light.	
E95																																			E95		
E96																																			E96		
E4361																																			E4361		
E4354																																			E4354		
IT																																			IT		
L87			X																																L87	Replaced Williams control throttle, pedal and sensor: Engine flush code 28: Pedal assembly part order out of Sacramento.	
P22A																																				P22A	
P22B																																				P22B	
P22C																																			P22C	B-service, replaced oil and air filters: Replaced front brake pads & rotors: Replaced all 4 tires.	
P4323																																				P4323	
P71																																				P71	
P74 523																																				P74 523	
P75 522																																				P75 522	
P77																																				P77	
P86																																				P86	
PIO-1																																				PIO-1	
POOL																																				POOL	
R4330																																				R4330	
R4332																																				R4332	
R4333																																				R4333	
R87																																				R87	Replaced d-side rear window regulator assembly.
Relief																																				Relief	
S4310																																				S4310	
SQ87																																				SQ87	R&R OBD2 connector: Repaired wiring for rear step lights: Repaired water leak on foam flow sensor.
T4327																																				T4327	

